From: Lynch Thomas
To: <u>fracking inquiry</u>
Subject: My thoughts

Date: Saturday, 18 March 2017 5:35:28 PM

To whom it may concern

The gas isn't going anywhere.

It will always be there and there will always be a demand.

Currently it requires 2-3 million litres of potable water per site.

On top of that 1% is "additives".

Chemical additives that prevent corrosion are not potable.

You then lose 10-30% of the gas during the process.

Find away to use non potable or recycled water. (grey water).

Do not use anti corrosion additives.

Capture 100% of the gas releasing non into the environment around the sights.

Then go for your life.

Until then don't.

Simple really.

Thank you

Thomas Lynch